



USB OUTPUT INTERFACE

100/200/300/400



100-11

- ◆ The cable without software, push the black button or footswitch, the data can be transferred into Excel, Word directly.
- ◆ The cable with software, the data can be transferred into the software at a set interval time automatically.



connect footswitch to transfer the data
(code: 400-01)

Code	Software	Products
100-11	Without	for digital calipers (refer to each product description)
100-12	With	
100-13	Without	
100-15	Without	for digital indicators(refer to each product description)
200-01	Without	
200-02	With	
200-03	Without	
200-04	With	for digital micrometers(refer to each product description)
300-01	Without	
300-03	Without	